	CONFIDENTIAL	79
-	Sanitized Copy Approved for Release 2011/04/19 : CIA-RDF CENTRAL INTELLIGENCE APPROXIMATION OF THE PROPERTY OF	REPORT 50X1-HUM
	information report	CD NO.
COUNTRY	USER (Black Sea)	DATE DISTR. 21 SEP 51
SUBJECT	Port of Tuapse	NO. OF PAGES 1
PLACE ACQUIRED		NO. OF ENCLS. 1 (LISTED BELOW)
DATE OF		SUPPLEMENT TO 50X1-HUM REPORT NO.
INFO.		NEI ON NO.
THIS POCUMENT OF THE UNITED U. S. C., IS AND OF IT'S CONTENT PIRITED OF LAW	IN SECTION BY ACTION OF AN ANTHONOMY SECTION OF SECTION AND ASSESSMENT OF THE PROPERTY OF THE	VALUATED INFORMATION
PIRITED OF LAT	HI AR L WHILE I PR CLINICALLY POPULATED.	NOT CIRCHIATE 50X1-HUM
		200 Marca
1.	water supply at this port and the water system is	there is an excellent well organized. Water is
,	sent from Tuapse to Novorossiisk. There were no signs of any antiaircraft defenses of	or fortifications of any
* •	kind in the port itself or the surrounding area. seen; however, very few soldiers were seen.	Many Soviet sailors were
3.	a number of Soviet vessels in the port	but no 50X1-HUM 50X1-HUM
4.	No foreign ships, other than those under the Ed to enter the port. Therefore, there is no Inflet Bulgarian vessel arrives at the port a representat agency at Novorossiisk to make the necessary arran necessary formalities.	agency; however, when a tive is sent from the Inflet
	Attachments: Sketch of the port of Tuapse.	Consideration and the constant of the constant
	September of Auditor Committee and	L Washington
		and the second s
		Total Control of Contr
		. Grand Control of the Control of th
		Acceptation 1999
	,	PATHICIAN COMPANY COMP
	CONFIDENTIAL	
	CLASSIFICATION CONTROL - US OFFIG	HALS ONLY
STATE ARMY	NAP' NSRE DISTRIBUTION AIR FBI	
	Docu	ment NoOLD
	No Ci	hange in Class. sclassified
	1	Changed Tot TS S 50X1-HUM
	Sanitized Copy Approved for Release 2011/04/19 : CIA-RDF	P82-00457R008500600011-4

CHATRAL INTALLIGANCE AGENCY

Key to the Sketch of the Port of Tuapse

- 1. The breakwater has been partially destroyed and has not as yet been repaired. No activity was seen on the breakwater.
- 2. The quay is being extended by approximately 100 meters. This is being done with reinforced concrete pylons and cement floorings. The work was not completed at the time of observation.
- 3. Two cranes of five tons each.
- 4. Large cement store for work being done on the quay.
- 5. The quay is damaged but is now undergoing repairs. At the moment it is dangerous to come alongside and there are constant accidents.
- 6. This part of the wharf is being rebuilt but it is not completed as yet.
- 7. Repair shop for merchant ships. This shop has been largely rebuilt and at the time of this report the 5,000-ton Soviet cargo steamer <u>Stary Bolsnevik</u> was being overhauled.
- 8. Anchored at this spot was a large submarine chaser and many patrol boats.
- 9. The oil wharf was in good condition. Alongside the wharf was the 10,000-ton Soviet tanker Mcskva. There is deep water alongside this wharf capable of taking ships up to 10,000 tons.
- 10. Breakwater constructed of huge stone blocks.
- 11. Large light which is visible at a distance of 15 miles. This point is known as kodoshe.
- 12. Buoy with a light.
- 13. Two lights. To enter the port shipping must navigate along the line between No. 12 and these two lights.
- 14. Two entrance lights red and green.

15.	Depth of	the water	alongsid	the quay	is 22-25	feet.	50X1-HUN	/

- 16. later depth is 25 feet here.
- 17. Anchored at this point was the lycco-ton Soviet cargo vessel Orac.

CONFIDENTIAL


TOWERDS - US OFFICIALS ONLY

50X1-HUM

CENTRAL INTELLIGENCE AGLICY

Attachment

Sketch of the Fort of Tuapse



MALY CONTROL - US OFFICIALS ONLY